

|             |  |  |
|-------------|--|--|
| SANTA FE    |  |  |
| FILE        |  |  |
| U.S.O.S.    |  |  |
| LAND OFFICE |  |  |
| OPERATOR    |  |  |

SANTA FE, NEW MEXICO 87501

5a. Indicate Type of Lease  
 State ☐ Fee ☒  
 5. State Oil & Gas Lease No.  
 N/A

**SUNDRY NOTICES AND REPORTS ON WELLS**

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" FORM C-101) FOR SUCH PROPOSALS.)

WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator  
 Hanson Operating Company, Inc.

Address of Operator  
 P. O. Box 1515, Roswell, New Mexico 88202-1515

Location of Well  
 UNIT LETTER E 1980 FEET FROM THE North LINE AND 560 FEET FROM

West LINE, SECTION 19 TOWNSHIP 22S RANGE 38E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)  
 3330.6' GR

7. Unit Agreement Name  
 N/A

8. Farm or Lease Name  
 Max Gutman

9. Well No.  
 8

10. Field and Pool, or Wildcat  
 Blinebry/Granite Wash

12. County  
 Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
 NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

|                                             |                                           |                                                     |                                               |
|---------------------------------------------|-------------------------------------------|-----------------------------------------------------|-----------------------------------------------|
| WELL REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/> | REMEDIAL WORK <input checked="" type="checkbox"/>   | ALTERING CASING <input type="checkbox"/>      |
| DEARILY ABANDON <input type="checkbox"/>    | CHANGE PLANS <input type="checkbox"/>     | COMMENCE DRILLING OPER. <input type="checkbox"/>    | PLUG AND ABANDONMENT <input type="checkbox"/> |
| OR ALTER CASING <input type="checkbox"/>    |                                           | CASING TEST AND CEMENT JOB <input type="checkbox"/> |                                               |
| OTHER <input type="checkbox"/>              |                                           | OTHER <u>Downhole Commingle DHC-707</u>             |                                               |

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed operations.) SEE RULE 1103.

On 11/03/88 the following work was performed:

- 1 - The bridge plug @ 6120', which isolated the Granite Wash perforations (7562-7475') from the Blinebry perforations (5871-5579'), was removed.
- 2 - The production string was run and the well placed back on production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Brenda R. Godfrey  
 Title Production Analyst  
 DATE 12/06/88

Orig. Signed by  
Paul Kautz  
 Geologist

DATE DEC 15 1988

COPIES OF APPROVAL, IF ANY:

RECEIVED

RECEIVED  
DEC 7 1980  
HOBBS

DEC 7 1980

DEC  
HOBBS