

INCLINATION REPORT

OPERATOR SUN Exploration & Production Co. ADDRESS P.O. BOX 1861, MIDLAND, TEXAS 79702
 LEASE NAME STATE "A" A/C 3 WELL NO. 10 FIELD Anglic Mattix 7 Rivers
Queen Grayburg
 LOCATION LEA COUNTY, NEW MEXICO

DEPTH	ANGLE INCLINATION DEGREES	DISPLACEMENT	DISPLACEMENT ACCUMULATED
457	$\frac{1}{4}$	2.0108	2.0108
866	$\frac{1}{4}$	1.7996	3.8104
1360	$\frac{1}{2}$	4.2978	8.1082
1854	$\frac{1}{2}$	4.2978	12.4060
2351	$\frac{3}{4}$	6.5107	18.9167
2847	1	8.6800	27.5967
2909	1	1.0850	28.6817
3407	$1\frac{1}{2}$	13.0476	41.7293
3717	$1\frac{3}{4}$	9.4550	51.1843
3800	$1\frac{3}{4}$	2.5315	53.7158

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.

CACTUS DRILLING COMPANY


Debbie Clark
 TITLE DEBBIE CLARK, OFFICE MANAGER

AFFIDAVIT:

Before me, the undersigned authority, appeared DEBBIE CLARK
 known to me to be the person whose name is subscribed herebelow, who, on making
 deposition, under oath states that he is acting for and in behalf of the operator
 of the well identified above, and that to the best of his knowledge and belief such
 well was not intentionally deviated from the true vertical whatsoever.

Debbie Clark
 AFFIANT'S SIGNATURE

Sworn and subscribed to in my presence on this the 20TH day of FEBRUARY, 1984



SEAL

Notary Public in and for the County
 of Lea, State of New Mexico