

INCLINATION REPORT

OPERATOR SUN Explorations Production Co. ADDRESS BOX 1861, MIDLAND TX 79702
 LEASE NAME STATE A A/C 1 #118 WELL NO. 118 FIELD Langley Mattix Sec 3
 LOCATION LEA CO. NM Sec 3, T-23S, R-36-E

DEPTH	ANGLE INCLINATION DEGREES	DISPLACEMENT	DISPLACEMENT ACCUMULATED
426	3/4	5.5806	5.5806
917	3/4	6.4321	12.0127
1447	1 1/4	11.5540	23.5667
1943	3/4	6.4976	30.0643
2440	1	8.6975	38.7618
2873	2	15.1117	53.8735
3337	2 1/2	20.2304	74.1039
3820	2 1/4	18.9819	93.0858

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.

CACTUS DRILLING COMPANY


Verena Oesch
 TITLE VERENA OESCH, OFFICE MANAGER

AFFIDAVIT:

Before me, the undersigned authority, appeared VERENA OESCH
 known to me to be the person whose name is subscribed herebelow, who, on making
 deposition, under oath states that he is acting for and in behalf of the operator
 of the well identified above, and that to the best of his knowledge and belief such
 well was not intentionally deviated from the true vertical whatsoever.

Verena Oesch
 AFFIANT'S SIGNATURE

Sworn ~~and subscribed to in my presence~~ on this the _____ day of _____, 19__



SEAL

Notary Public in and for the County
 of Lea, State of New Mexico