

INCLINATION REPORT

OPERATOR SUN Exploration + Production Co. ADDRESS BOX 1861, MIDLAND, TX 79702
 LEASE NAME ST. "A" A/C 1 WELL NO. #120 FIELD Langlie Muttix Seven Rivers Duren Grayburg
 LOCATION Unit Ltr "C" Sec. 10, T-23-S, R-36-E

DEPTH	ANGLE INCLINATION DEGREES	DISPLACEMENT	DISPLACEMENT ACCUMULATED
442	3/4	5.7902	5.7902
922	3/4	6.2880	12.0782
1419	1	8.6975	20.7759
1917	1/2	4.3326	25.1083
2415	2	17.3802	42.4885
2912	3	25.9931	68.4816
3255	2 1/2	14.9548	83.4364
3751	2 1/4	19.4928	102.9292
3850	2 1/4	3.8907	106.8199

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.

CACTUS DRILLING COMPANY

Debra Kelly


TITLE OFFICE MANAGER

AFFIDAVIT:

Before me, the undersigned authority, appeared DEBRA KELLY
 known to me to be the person whose name is subscribed herebelow, who, on making deposition, under oath states that he is acting for and in behalf of the operator of the well identified above, and that to the best of his knowledge and belief such well was not intentionally deviated from the true vertical whatsoever.

Debra Kelly
 AFFIANT'S SIGNATURE

Sworn and subscribed to in my presence on this the _____ day of _____, 19____



SEAL

Notary Public in and for the County
 of Lea, State of New Mexico