

INCLINATION REPORT

OPERATOR SUN Exploration & Production Co. ADDRESS P.O. BOX 1861, MIDLAND, TEXAS 79702
 LEASE NAME STATE A A/C 1 WELL NO. 121 FIELD Langlie Mattix Seven Rivers
Queen Grayburg
 LOCATION LEA COUNTY, NEW MEXICO

DEPTH	ANGLE INCLINATION DEGREES	DISPLACEMENT	DISPLACEMENT ACCUMULATED
473	$\frac{1}{4}$	2.0812	2.0812
959	$\frac{1}{2}$	4.2282	6.3094
1457	$\frac{3}{4}$	6.5238	12.8332
1982	1	9.1875	22.0207
2478	$1\frac{1}{4}$	10.8128	32.8335
2845	2	12.8083	45.6418
3319	$1\frac{3}{4}$	14.4570	60.0988
3800	2	16.7869	76.8857

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.

CACTUS DRILLING COMPANY

Debbie Clark

TITLE DEBBIE CLARK, OFFICE MANAGER

AFFIDAVIT:


Before me, the undersigned authority, appeared DEBBIE CLARK
 known to me to be the person whose name is subscribed herebelow, who, on making
 deposition, under oath states that he is acting for and in behalf of the operator
 of the well identified above, and that to the best of his knowledge and belief such
 well was not intentionally deviated from the true vertical whatsoever.

Debbie Clark

AFFIANT'S SIGNATURE

Sworn and subscribed to in my presence on this the 27TH day of FEBRUARY, 19 84

SEAL



Notary Public in and for the County
 of Lea, State of New Mexico

4 /

RECEIVED
APR 9 1984
O.C.D.
HOBBS OFFICE