

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. Oil Cons.
P.O. Box 1980
Hobbs, NM 88241

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT --" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well: ☒ OIL WELL ☐ GAS WELL ☐ OTHER

2. Name of Operator
TEXACO EXPLORATION & PRODUCTION INC.

3. Address and Telephone No. 205 E. Bender, HOBBS, NM 88240 397-0418

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Unit Letter M : 660 Feet From The SOUTH Line and 860 Feet From The
WEST Line Section 18 Township 23-S Range 32-E

5. Lease Designation and Serial No.
NM 18848

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and Number
SDE 18 FEDERAL
2

9. API Well No.
30-025-32669

10. Field and Pool, Exploratory Area
SAND DUNES; DELAWARE, EAST

11. County or Parish, State
LEA, NM

12. Check Appropriate Box(s) To Indicate Nature of Notice, Report, or Other Data

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Attering Casing
☒ OTHER: EXTENSION OF TA STATUS
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log Form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Texaco Exploration and Production Inc requests an extension of one year of the temporary abandonment status of the above well which will end on 4/16/98. The original temporary abandonment status was requested on 4/1/98 based upon the results of a casing integrity test conducted on 4/16/97. The CIBP set @ 4601' was successfully tested to 500 psi for 30 minutes. TEPI requests TA status on this well through 4/16/99. A copy of the 4/16/97 test chart is on back.

Contacts:
Jason Wacker, Engineer, 397-0484
Ray Short, Carlsbad Field Management Team Leader, 837-5676

TA APPROVED FOR 12 MONTH PERIOD
ENDING APR 16 1999

14. I hereby certify that the foregoing is true and correct.

SIGNATURE Monte C. Duncan TITLE Engr Asst DATE 4/1/98
TYPE OR PRINT NAME Monte C. Duncan

(This space for Federal or State office use)

APPROVED BY ORIG. SGD. DAVID E. GLASS TITLE PETROLEUM ENGINEER DATE APR 13 1999
CONDITIONS OF APPROVAL, IF ANY:

