

|                                           |                                 |                        |
|-------------------------------------------|---------------------------------|------------------------|
| WELL TEST INTERPRETATION REPORT #: 138445 |                                 | PAGE: 3.               |
| CLIENT : MYCO IN INC.                     |                                 | 18-SEP-95              |
| REGION : CSD                              | SEQUENCE OF EVENTS<br>Continued | FIELD: DELAWARE        |
| DISTRICT: MIDLAND                         |                                 | ZONE : ABALON SAND     |
| BASE : MIDLAND                            |                                 | WELL : SHARBAO FED. #1 |
| ENGINEER: J. DAUGHERTY                    |                                 | LOCATION: S7T23S-A32E  |

| DATE  | TIME<br>(HR:MIN) | DESCRIPTION | ET<br>(MINS) | BHP<br>(PSIA) | WHP<br>(PSIG) |
|-------|------------------|-------------|--------------|---------------|---------------|
| ===== |                  |             |              |               |               |

|       |                 |     |      |  |  |
|-------|-----------------|-----|------|--|--|
| 17:04 | END SHUT-IN     | 635 | 3431 |  |  |
| 17:05 | HYDROSTATIC MUD | 636 | 3807 |  |  |