

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. Oil Cons. Division
P.O. Box 1980
Hobbs, NM 88241
FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993
Bureau Designation and Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

RECEIVED

1991 MAY 23 10:35

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

MYCO INDUSTRIES, INC.

3. Address and Telephone No.

P.O. BOX 840, Artesia, NM 88210

(505) 748-4260

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1980' FNL & 660' FEL Unit H

SECTION 7-T23S-R32E

BUREAU OF LAND MGMT
ROSWELL OFFICE

7. If Unit or CA, Agreement Designation

8. Well Name and No.

BITSY FEDERAL #1

9. API Well No.

30-025-33398

10. Field and Pool, or Exploratory Area

SAND DUNES BONE SPRING

11. County or Parish, State

LEA, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

ACCEPTED FOR RECORD

MAY 20 1997

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other PERFS/TEST DELAWARE

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

4/10/97 PERF'D (1 JSPF) AS FOLLOWS: 8350', 59', 63', 65', 8460', 82', 84', 90', 94' AND 99' - TOTAL 10 HOLES (0.38") - LOWER BRUSHY CANYON "X" AND "Z" SANDS. ACIDIZED PERFS 8350-8499' WITH 2000 GALS 7.5% HCL + BALLS.

4/18/97 RE-PERF 8460', 8482', 8484', 8490', 8494', and 8499' (2 JSPF) TOTAL - 12 HOLES (0.38"). ACIDIZED PERFS 8460-8499', WITH 2000 GALS 7.5% HCL + BALLS.

/19-22/97 SWAB TEST 8350-8499' AND ESTABLISH FLUID ENTRY @ 300' PER HR. W/5-10% OIL CUT.

4/24/97 RETURN TO PUMPING FROM PERFS 8350-8499' (DELAWARE), 8679-91' AND 8978-9137' (AVALON SAND & BONE SPRING). S/N @ 8251'.

CERTIFIED RETURN: P 387 148 437

14. I hereby certify that the foregoing is true and correct

Signed Isabel Lopez

Title ENG. TECHNICIAN

Date 5/22/97

(This space for Federal or State office use)

Approved by _____
Conditions of approval, if any:

Title _____

Date _____