

1963)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42 R-1
5. LEASE DESIGNATION AND SERIAL NO.
NM-01917
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR Bill J. Graham		8. FARM OR LEASE NAME Hanagan D	
3. ADDRESS OF OPERATOR Box 5321, Midland, Texas 79701		9. WELL NO. 4 Unit Letter F	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980 FNL & 1980 FWL		10. FIELD AND POOL, OR WILDCAT Double X Delaware	
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 11, T-24-S, R-32E		12. COUNTY OR PARISH Lea	
14. PERMIT NO. 30-025-08143		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3645	
16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data		13. STATE NM	

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	MULTIPLE COMPLETE	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	ABANDON*	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
(Other)			

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
FRACTURE TREATMENT	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
SHOOTING OR ACIDIZING	<input type="checkbox"/>	ABANDONMENT*	<input checked="" type="checkbox"/>
(Other)			

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of start, and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

Abandonment:

1-17-74 - spotted 25 sx plug at 4900' with tubing, filled hole with Sat. brine w/salt gel, pulled tubing.
1-18-74 - shot 4 1/2" casing @ 4016', pulled same. ran 2 3/8" tubing to 3980', spotted 35 sx plug, pulled to 1400', spotted 35 sx plug.
1-19-74 - spotted 35 sx at 370', 10 sx in surface with marker.

Location has been cleaned up and caliche pad ripped.

Casing left in hole - 4 1/2" from 5006' to 4016'
8 5/8" from surface to 367'

Old perf. - notch @ 4970'

18. I hereby certify that the foregoing is true and correct

SIGNED Bill J. Graham
(This space for Federal or State office use)

TITLE Owner

DATE 9-18-74

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____

APPROVED
OCT 18 1974
ARTHUR R. BROWN
DISTRICT ENGINEER

*See Instructions on Reverse Side

ADT 30-025-08143