Charles Internal Property

(SUBMIT IN TRIPLICATE)

UNITED STATES

DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Lease No. 11.

SUNDRY NOTICES AND REPORTS ON WELLS

| OTICE OF INTENTION TO DRILL | SUBSEQUENT REPORT OF WATER SHUTFOFF |
|---|--|
| OTICE OF INTENTION TO CHANGE PLANS | SUBSEQUENT REPORT OF SHOOTING OR ACIDITING |
| OTICE OF INTENTION TO TEST WATER SHUT-OFF | SUBSEQUENT REPORT OF ALTERING CASING |
| OTICE OF INTENTION TO RE-DRILL OR REPAIR WELL | SUBSEQUENT REPORT OF RE-DRILLING OF REPAIR |
| NOTICE OF INTENTION TO SHOOT OR ACIDIZE | SUBSEQUENT REPORT OF ABANDONMENT |
| OTICE OF INTENTION TO PULL OR ALTER CASING | SUPPLEMENTARY WELL HISTORY |
| IOTICE OF INTENTION TO ABANDON WELL | |
| 1 | |
| | OTICE OF INTENTION TO CHANGE PLANS OTICE OF INTENTION TO TEST WATER SHUT-OFF OTICE OF INTENTION TO RE-DRILL OR REPAIR WELL OTICE OF INTENTION TO SHOOT OR ACIDIZE OTICE OF INTENTION TO PULL OR ALFER CASING |

FINDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA

| Pederal-E | aregen | n _E n | | | Aug | ust 3 | | 19 61 |
|-----------------|---------------------|------------------|--------------|------------|--------------------------|-------------|--|-------|
| Well No. | š | is located | 193 0 | ft. from | ${N \choose S}$ line and | 660 (L. fro | $\operatorname{sm}\left(\frac{\mathbb{E}}{ \mathbf{x} }\right)$ line of sec . | 15 |
| SF/4 (9/ Sec | 15 and See. No.: | | 24 S | 32 | Kanke) | (Meridian) | | |
| Double-X | (Field) | | Lea | (County or | Subdivision) | Nev | Mexico Litate or Terribusy | |

The elevation of the derrick floor above sea level is 3588 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well was completed dry at a total depth of 4970' on 7-10-61.

Spotted 20 sacks cement from 4904' to 4800'; mad to 4415'; 15 sacks cement 4415' to 4140'; shot 4-1/2" casing & 4140'; pulled and recovered ease; pumped must be 1400'; spotted 25 sacks cement \$ 1400'; did not hold, spotted 25 sacks cement & 1400'; after 9 hrs found plug \$ 1000'; mud to 1160'; did not hold, spotted 25 sacks cement \$11400'; after 9 hrs found plug \$ 1000'; mud to 1160'; did not hold, spotted 25 sacks cement \$1160'; did not hold; spotted 25 sacks cement \$1160'; did not hold; spotted 25 sacks cement \$1160'; top of plug \$ 1045'; mud \$1.50'; 25 sacks cement \$450'; top of plug \$ 350'; mud to 50'; 10 sacks cement to surface. \$405' of 8-5/8" & 766' of 4-1/2" casing was left in hole. Set marker and abandon. Location is cleaned up and ready for inspection.

PAINIT

CP . 95 1140

| I understant | d that this plan of rock must receive approval in wri | II I HIBLE | . amenced. |
|--------------|--|--------------------|------------|
| | Oulf Oil Corporation | | • • |
| Address | P. O. Box 766 | V | |
| | Kermit, Texas | $B_{\mathbf{y}}$, | |
| | and the second s | Title Arm Indone | 94 9 |