

(SUBMIT IN TRIPLICATE)


Land Office **New Mexico**

Lease No. **LC 062269A**

Unit **200**

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

NOV 21 AM 11 27



## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

**November 17,** 19 **62**

Well No. **3** is located **660** ft. from **{N}** line and **660** ft. from **{E}** line of sec. **22**  
**{S}** **{W}**

**NE/4 NE/4 Sec. 22**  
( $\frac{1}{4}$  Sec. and Sec. No.)

**24S**  
(Twp.)

**32E**  
(Range)

**NMPM**  
(Meridian)

**Double-X Delaware**  
(Field)

**Lee**  
(County or Subdivision)

**New Mexico**  
(State or Territory)

The elevation of the derrick floor above sea level is **3594** ft.

### DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

**T.D. 390. Ran 12 joints 8-5/8" 24# J-55 Casing to total depth. Cemented with 200 sacks Regular cement with 2% NA-5. Circulated 15 sacks. W.O.C. 24 hours. Tested 1000 lbs. no pressure drop. Drilled out.**

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Charles B. Read**

Address **Box 1822**

**Roswell, New Mexico**

By

Title **Operator**