U.S. GEOLOGICAL SURVEY ROSWELL, NEW MEXICO

Form 9-331 Form Approved. Dec. 1973 Budget Bureau No. 42-R1424 UNITED STATES 5. LEASE LC DEPARTMENT OF THE INTERIOR 065876 **GEOLOGICAL SURVEY** 6. IF INDIAN, ALLOTTEE OR TRIBE NAME 7. UNIT AGREEMENT NAME SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.) 8. FARM OR LEASE NAME NORTH EL MAR UNIT well well other 2. NAME OF OPERATOR CONOCO INC 10. FIELD OR WILDCAT NAME 3. ADDRESS OF OPERATOR EL MAR DELAWARE P. O. BOX 460, HOBBS, N.M. 88240 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 11. SEC., T., R., M., OR BLK. AND SURVEY OR **AREA** SEC 24, T-265, R-32E AT SURFACE: 640 FSL & FEL 12. COUNTY OR PARISH 13. STATE AT TOP PROD. INTERVAL: AT TOTAL DEPTH: -14. API NO. 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE. REPORT, OR OTHER DATA 15. ELEVATIONS (SHOW DF, KDB, AND WD) REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (NOTE: Report results of multiple completion or zone PULL OR ALTER CASING change on Form 9-330.) MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) Csq. /eak 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* Csg. leak survey was performed on subject well w/ Valles being dug up d tagged at the surface. Survey was Subsurface Safety Valve: Manu. and Type _ 18. I hereby certify that the foregoing is trife and correct TITLE ADMIN. SUPERVISOR DATE (This space for Federal or State office use) APPROVED BY CONDITIONS OF APPROVAL, IF ANY: JUN 1 6 1980 4565-5

*See Instructions on Reverse Side