Form 9-331 Dec. 1973

| Form | Approved.    |    |      |
|------|--------------|----|------|
| Ruda | at Burnau Na | 40 | D140 |

| UNITED STATES  | Budget Bureau No. 42-R1424  |
|--|---|
| DEPARTMENT OF THE INTERIOR   | 5. LEASE  |
|  | LC 069515   |
| GEOLOGICAL SURVEY  | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME  |
| SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir, Use Form 9–331–C for such proposals.)                                     | 7. UNIT AGREEMENT NAME  |
| proposals.)  | 8. FARM OR LEASE NAME   |
| 1. oil gas well other in i   | NORTH EL MAR UNIT   |
| the the the  | 9. WELL NO.   |
| 2. NAME OF OPERATOR  | 3/  |
| CONOCO INC.  3. ADDRESS OF OPERATOR  | 10. FIELD OR WILDCAT NAME   |
|  | EL MAR DELAWARE   |
| P. O. BOX 460, HOBBS, N.M. 88240  4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)   | 11. SEC., T., R., M., OR BLK. AND SURVEY OF AREA  |
| AT SURFACE: 660 FSL & 1980 FWL   | SEC. 26, T-265, R-32E   |
| AT TOP PROD. INTERVAL:   | 12. COUNTY OR PARISH 13. STATE  |
| AT TOTAL DEPTH:  | 14. API NO.   |
| 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,  | AFINO,  |
| REPORT, OR OTHER DATA  | 15. ELEVATIONS (SHOW DF, KDB, AND WD)   |
| REQUEST FOR APPROVAL TO: SUBSPOLIENT REPORT OF   | An F  |
| TEST WATER SHUT OFF SUBSEQUENT REPORT OF:  | W The same of the |
| FRACTURE TREAT   |   |
| SHOOT OR ACIDIZE   |   |
| REPAIR WELL  | (NOTE: Report results of multiple completion or zone  |
| MULTIPLE COMPLETE  | change on Form 9-330.)  |
| CHANGE ZONES   |   |
| ABANDON*   | 그 그 그 그 그 사람들이 얼마를 보는 것 같습니다.   |
| (other) Csq. leak survey   | 그 그 그 이 그 연습원장 그 의 이상에는 그런  |
| 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is directly measured and true vertical depths for all markers and zones pertinent | all pertinent details, and give pertinent dates, rectionally drilled, give subsurface locations and to this work.)*   |
|  |   |
| Csq. leak survey was performed on subject well w/  |   |
| January was  | <b>─</b>  |
| performed on subject well w/   |   |
| steller in the   |   |
| Valles being dug up dragged at   |   |
| the such s   | * 494   |
| the surface. Survey was  |   |
| witnessed by Tony Plattsmer  |   |
| of NMOED.  |   |
| or mines.  |   |
| Subsurface Safety Valve: Manu. and Type  | 2   |
|  | Set @ Ft.   |
| 18. I hereby certify that the foregoing is trife and correct   |   |
| SIGNED WM G. Butler fold TITLE ADMIN SUPERVISE   |   |
|  | ACCEPTED FOR DECOME   |
| (This space for Federal or State office  | use)  |
| APPROVED BY TITLE  | DATE TIN 1 C 1000   |
| CONDITIONS OF APPROVAL, IF ANY:  4565-5  | JUN 1 6 1980  |
|  |   |
|  | U.S. GEOLOGICAL SURVEY  |

\*See Instructions on Reverse Side

U.S. GEOLÓGICÁL SURVEY ROSWELL, NEW MEXICO