



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office _____

Lease No. LC 071-85

Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL _____	SUBSEQUENT REPORT OF WATER SHUT-OFF _____	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS _____	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING _____	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF _____	SUBSEQUENT REPORT OF ALTERING CASING _____	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL _____	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR _____	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE _____	SUBSEQUENT REPORT OF ABANDONMENT _____	
NOTICE OF INTENTION TO PULL OR ALTER CASING _____	SUPPLEMENTARY WELL HISTORY _____	
NOTICE OF INTENTION TO ABANDON WELL _____		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 21, 1959

Well No. 1 is located 130 ft. from [N] line and 100 ft. from [E] line of sec. 34
NE/4 SE/4 (Lot 1) Sec. 34 14-5 12-0 NMPN
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Undesignated 100 New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3,111 ft. All measurements taken from ground at 3,101 feet.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded June 26, 1958

6-26-59 - Ran 273.11 feet of 3-5/8 inch casing. Set at 174 feet ground level and cemented with 125 sacks of regular cement with 2% gel in first 75 sacks and 2% calcium chloride in last 50 sacks. Cement circulated.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company George L. Buckles Company

Address P. O. Box 307

Monahans, Texas

By Robert M. Orr

Title Chief Engineer