



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Budget Bureau No. 42-R358.4.  
Form Approved.

Land Office Las Cruces  
Lease No. NM0127A  
Unit Lease

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 22, 19 52

Goedeknecht

Well No. 3 is located 455 ft. from N line and      ft. from E line of sec. 16

N 1/4 of 26/4 Sec. 16 (1/4 Sec. and Sec. No.) 2 (Twp.) 1 (Range) 12 (Meridian)

Salado Draw (Field) 1952 (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is      ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded 9:30 P.M., 10-10-52. Drilling to 100'. Ran 12 jts. 7 1/2" O.D. 24-15. H-40 casing. Casing set at 100' and cemented with 200 sacks, reg. neat cement. 2100 down to 100'. 11-17-52. Cement circulated. 700 24 hours. Tested static with 100 lbs. for 5 min. Tested O.K.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Continental Oil Co.

Address Box 427

Robbs, New Mexico

By [Signature]

Title District Superintendent

UAC (3) NM001 (1) 100-114