

NUMBER OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
TRANSPORTER	OIL GAS
PRODUCTION OFFICE	
OPERATOR	

30-025-08424

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company El Cinco Production Co., Ltd		Address Box 1026 Midland, Texas	
Lease Humble-Madera	Well No. 1	Unit Letter U	Section 23
Date Work Performed 11-1-60	Pool Wildcat	Township 26	Range 33
		County Lea	

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations
 ☐ Casing Test and Cement Job
 ☐ Other (Explain):
- ☒ Plugging
 ☐ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

Verbal permission to plug was given 10-31-60 by Eric I. Engbrecht. Hole was filled with mud and cement plugs spotted with drill pipe as follows:

5325 - 25 sacks
5110 - 25 sacks
1100 - 25 sacks
390 - 25 sacks
Surface - 10 sacks

Marker was erected in surface as required and drillsite cleaned and pits covered.

Witnessed by Jim Richards	Position Geologist	Company El Cinco Production Co., Ltd
-------------------------------------	------------------------------	--

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA

D F Elev.	T D	P B T D	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open Hole Interval			Producing Formation(s)	

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Approved by <i>John W. Ryan</i>	Name <i>Bill Green</i>
Title	Position Office Manager
Date	Company El Cinco Production Co., Ltd