

NUMBER OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
TRANSPORTER	OIL GAS
PRODUCTION OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company El Cinco Production Co., Ltd				Address Box 1026 Midland, Texas			
Lease Humble - Madera	Well No. 1	Unit Letter N	Section 23	Township 26	Range 33		
Date Work Performed 10-23-60	Pool Undesignated			County Lea			

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations
 ☒ Casing Test and Cement Job
 ☐ Other (Explain):
☐ Plugging
 ☐ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

Spudded 10-22-60: Set 383 Ft 24 lb per foot smls pittsb. casing, cemented with 250 sacks 4% gel and 50 sacks regular cement around shoe. Let cement cure 36 hours and tested with 1000 pounds for 30 minutes with no bleed off.

Witnessed by S. O. Lamb	Position Tool Pusher	Company Dual Drilling Company
-----------------------------------	--------------------------------	---

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA


D F Elev.	T D	P BTD	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open Hole Interval		Producing Formation(s)		

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Approved by 	Name Bill D. Green
Title	Position Office Manager
Date	Company El Cinco Production Co., Ltd