

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-09403
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name State A A/C 1
8. Well No. 25
9. Pool name or Wildcat Jalmat-Tansill-Yts 7 Rvrs
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GL - 3344

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☐ GAS WELL ☒ OTHER ☐ 4710	2. Name of Operator Clayton W. Williams, Jr., Inc.
3. Address of Operator Six Desta Drive, Suite 3000 Midland, Texas 79705	4. Well Location Unit Letter F : 1650 Feet From The North Line and 1650 Feet From The West Line Section 24 Township 23S Range 36E NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GL - 3344	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	COMMENCE DRILLING OPNS. ☐
PULL OR ALTER CASING ☐	CASING TEST AND CEMENT JOB ☐
OTHER: ☐	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6/92 - Set CIBP @ 2775'. Dumped 2 sx cement on CIBP.

9/16/92 - Isolate csg leaks from 320 - 907'. Received verbal plugging instructions from Jerry Sexton - OCD (9/17).

9/17/92 - Circulated 9.5 PPG gelled brine from 2730' to surface. Spot 100 sx balanced plug from 560-935'. Perf 8-5/8" csg @ 315', 2 SPF. Were Unable to circulate up 13-3/8, 8-5/8" annulus. Found 1949 report, (copy attached), showing 500 sx cement pumped down annulus. Pump 125 sx Class A w/2% CaCl2 down csg. Dug out and cut wellhead and anchors. Set Plug & Abandon Marker.

WELL PLUGGED AND ABANDONED

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE David G. Grafe TITLE Petroleum Engineer DATE 9/18/92
TYPE OR PRINT NAME David G. Grafe TELEPHONE NO. 682-6234

(This space for State Use)

APPROVED BY Charles P. ... TITLE OIL & GAS INSPECTOR DATE AUG 13 1993
CONDITIONS OF APPROVAL, IF ANY: