


NMOCC

Form 9-331a  
(Feb. 1951)

Budget Bureau 42-R358.3.  
Approval expires 12-31-55.



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Las Cruces  
Lease No. 11 030139a  
Unit 1440

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	XX
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Lynn 1-27

January 21, 1957

Well No. 2 is located 2310 ft. from N line and 330 ft. from W line of sec. 27

4 1/4 Sec 27  
(1/4 Sec. and Sec. No.)

23N 30E  
(Twp.) (Range)

Range  
(Meridian)

Jalisco  
(Field)

Lee  
(County or Subdivision)

New Mexico  
(State or Territory)

The elevation of the derrick floor above sea level is \_\_\_\_\_ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded 1-1-57. Ran 13 joints of 5/8" casing set at 365' with 350 sacks, cement circulated. Plug down 1-1-57. Tested casing with 1000' before and after drilling plug. Tested OK.

Ran 5 1/2" casing set at 3549' with 1350 sacks. Top of cement 1425'. Plug down 1-15-57. Tested casing with 1000' before and after drilling plug. Tested OK.

ILLEGIBLE

I understand that this plan of work must receive approval in writing

menced.

Company Continental Oil Company

Address Box 68

Alameda, New Mexico

By \_\_\_\_\_

Title District Superintendent