

Form 7-332a  
(March 1942)

TRIPPLICATE

(SUBMIT IN TRIPPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office New Mexico

Lease No. 030139 (a)

Unit P

RECEIVED

AUG 30 1951

OIL CONSERVATION COMMISSION  
HOBBBS OFFICE

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 20, 1951

Well No. 2 Lynn is located 290 ft. from S line and 330 ft. from E line of sec. 28

SE 1/4 Sec. 28  
(1/4 Sec. and Sec. No.)

235  
(Twp.)

36E  
(Range)

S 40  
(Meridian)

Cooper-Jal  
(Field)

Lee  
(County or Subdivision)

New Mexico  
(State or Territory)

The elevation of the derrick floor above sea level is 3355 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Found top of 7" casing cement plug at 3622'. It was not necessary to drill out cement plug. Tested casing with 1000 psi pressure for 30 minutes and the pressure dropped 30 psi. Now preparing to perforate casing and acidize.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Kan-Mex Corporation

Address 1203 Dallas National Bank Building

Dallas, Texas

By J. D. Simon

Title Petroleum Engineer