

(SUBMIT IN TRIPLICATE)  
UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Las Cruces  
Lease No. 0 30139 (a)  
Unit C

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 7, 1952

Well No. 4 is located 330 ft. from N line and 2310 ft. from E line of sec. 28  
NE 1/4 N 1/4 23-8 35-E N.T.S.M.  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Cooper-Jal Lee New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3350 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Before drilling plugs, tested casing with 1000 P.S.I. for 30 minutes and pressure dropped 15 P.S.I. Drilled cement plugs and tested with 1000 P.S.I. pressure for 30 minutes and pressure dropped 20 P.S.I.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Kan-Mex Corporation  
Address 1203 Dallas National Bank Bldg.  
Dallas, Texas  
By R. DeChicchia  
Title Geologist