

NEW MEXICO OIL CONSERVATION COMMISSION
Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Report by Checking Below

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF PLUGGING WELL		REPORT ON RECOMPLETION OPERATION	A	REPORT ON (Other)	

December 17, 1952 Hobbs, New Mexico
(Date) (Place)

Following is a report on the work done and the results obtained under the heading noted above at the

State of New Mexico, Well No. 1 in the 1/4 Sec. 33, T.23S., R. 30W., NMPM., Pool, Lea County.
(Company or Operator) (Lease)
(Contractor)

The Dates of this work were as follows: 11-5-52 thru 11-13-52

Notice of intention to do the work (was) ~~was not~~ submitted on Form C-102 on 11-5-52, 1952, and approval of the proposed plan (was) ~~was not~~ obtained.
(Cross out incorrect words)

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

We set bridge plug at 3490' and dumped hydramite to 3490' to shut off bottom hole water. After bottom hole shut off was obtained we cemented from 3430' to 3480' in the 4" hole. No more work was done. Well to be finally abandoned.

Witnessed by Charlie Blumhore (Name) (Company) (Title)

Approved: OIL CONSERVATION COMMISSION

Ray [Signature]
(Name)
(Title) (Date)

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name: [Signature]
Position: [Signature]
Representing: [Signature]
Address: [Signature]