

## NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

## MISCELLANEOUS REPORTS ON WELL

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut-offs, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of report by checking below:

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL		REPORT ON PULLING OR OTHERWISE ALTERING CASING	
REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON DEEPENING WELL	
REPORT ON RESULT OF PLUGGING OF WELL	<b>V</b>		

Wink, Texas January 23, 1943

Place

Date

OIL CONSERVATION COMMISSION,  
Santa Fe, New Mexico.

Gentlemen:

Following is a report on the work done and the results obtained under the heading noted above at the

General Crude Oil Company

State "F"

Well No. 1

NW 1

in the NW 1

Company or Operator

Lease

of Sec. 2

T. 24

R. 36

N. M. P. M.,

Cooper

Field,

Lea

County

The dates of this work were as follows:

1/8/43 to 1/16/43

Notice of intention to do the work was (~~was~~) submitted on Form C-102 on Oct. 20th, 1942  
and approval of the proposed plan was (~~was not~~) obtained. (Cross out incorrect words)

## DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

Intentions were to plug and pull all 5½" and 7-5/8" Casing possible.

Work Done:- Plugged off bottom of hole at 3754' back up in 5½" Casing w/ 14 Tons mud, 40 sks, cement and 60# Jel-Flex. Shoot 5½" Casing off and pulled 2020'. Filled all open hole with Mud and cement up into 7-5/8" Casing. Which confine permanently all oil, gas and water sections originally containing them. Shoot and pull 275' of 7-5/8" Casing and filled hole with Mud and cement back to surface. Set a 4" marker in cement, up 4' above ground level. Cellar filled and location cleared off.

Witnessed by \_\_\_\_\_ Name \_\_\_\_\_ Company \_\_\_\_\_ Title \_\_\_\_\_

Subscribed and sworn to before me this

I hereby swear or affirm that the information given above is true and correct.

25. day of Jan. 1943.

Name Jane Hildreth

D. O. M. Adov

Position Dist. Supt.,

Notary Public

Representing General Crude Oil Company

Company or Operator

My Commission expires

June 1-1943

Address Box # 685, Wink, Texas.

Remarks:

Roy Garbrough  
Name  
Oil and Gas Inspector  
Title