

FROM-	TO-	TOTAL FEET	FORMATION
0	60		Caliche
60	125		Caliche and Sand
125	239		Sand and Redrock
239	425		Sand and Shale
425	650		Redrock
650	690		Gravel
690	830		Redrock
830	890		Sand
890	1174		Redrock
1174	1250		Redrock and Blue Shale
1250	1325		Redrock
1325	1438		Anhydrite and Gyp
1438	1735		Anhydrite and Salt
1735	1779		Anhydrite
1779	2286		Anhydrite and Salt
2286	2291		Anhydrite
2291	2365		Salt and Anhydrite
2365	2550		Anhydrite
2550	2620		Salt
2620	2710		Salt and Anhydrite
2710	2926		Lime
2926	2944		Broken Lime
2944	3347		Lime
3347	3380		Broken Lime
3380	3412		Lime
3412	3471		Broken Lime
3471	3500		Broken Lime Porous Showing Gas
3500	3532		Brown-Lime Porous Pay from 3503 to 3532

Drill Stem Test from 3471 to 3505 showed 3,220,000 cu. ft. gas and show of oil, reamed hole to 3498 and ran 5 1/2" casing set at 3496 cemented.

Drilled hole from 3503 to 3532 with oil under pressure. Tested well at 3432; flowed 32 1/2 bbls. oil per hour thru casing. 6 1/2 million cu. ft. of gas, with drill stem in hole. Ran 2 1/2" tubing to bottom and tested well flowing thru 1" choke for 24 hours; made 691 bbls. oil, 1 million cu. ft. of gas. T.P. 25 pounds. C.P. 375 pounds.

LOGS USED					

SHOOTING RECORD					

PLUGS AND BRIDGES					

MIDDING AND CEMENTING RECORD					

HISTORY OF OIL OR GAS WELL					

It is of the greatest importance to have a complete history of the well. Please state in detail the dates of redrilling, together with the reasons for the work and its results. If there were any changes made in the casing, state fully, and if any casing was "sidetracked" or left in the well, give its size and location. If the well has been dynamited, give date, size, position, and number of shots. If plugs or bridges were put in to test for water, state kind of material used, position, and results of pumping or bailing.

CASING RECORD					

IMPROVEMENTS AND SANDS					

OIL OR GAS SANDS OR ZONES					

Completed drilling _____

The summary on this page is for the condition of the well at above date.

Date _____

Signature _____

As far as can be determined from all available records.

The information given hereafter is a complete and correct record of the well and all work done thereon.

Location _____

Well No. _____

Owner _____

Company _____

Address _____