

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Las Cruces**
Lease No. **LC 030467 a**
Unit **REDFU**

SUNDRY NOTICES AND REPORTS ON WELLS

| | |
|--|--|
| NOTICE OF INTENTION TO DRILL | SUBSEQUENT REPORT OF WATER SHUT-OFF |
| NOTICE OF INTENTION TO CHANGE PLANS | SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF | SUBSEQUENT REPORT OF ALTERING CASING |
| NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL | SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR |
| NOTICE OF INTENTION TO SHOOT OR ACIDIZE | SUBSEQUENT REPORT OF ABANDONMENT |
| NOTICE OF INTENTION TO PULL OR ALTER CASING | SUPPLEMENTARY WELL HISTORY |
| NOTICE OF INTENTION TO ABANDON WELL | |

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

VOLUME 1-14, _____ November 13, 1956
 Well No. 6 is located 1960 ft. from $\begin{Bmatrix} N \\ S \end{Bmatrix}$ line and 1960 ft. from $\begin{Bmatrix} E \\ W \end{Bmatrix}$ line of sec. 14
 24 36 36 36
 (Twp.) (Range) (Meridian)
 Jalant Lee New Mexico
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

This well was plugged and abandoned on 11-12-56 in the following manner: TD Line 3502', PB 3185', 5 1/2" casing set at 3479'. Squeezed perforations 3180-2965', set cement plug 3185-2675', 12" mud 1875-1875', 50 sack cement plug 1875-1825', 12" mud 1825-50', 50 sack cement plug 50-0'. A 4' marker was installed at surface and the surface restored to original condition. Plugging started 11-4-56, completed 11-12-56. All of the 10 3/4" casing, 230' 10", and the 7 5/8" casing, 1703' 8", was left in the hole; 1869' of the 5 1/2" casing was pulled leaving 1617' 1" in the hole. Before plugging this well was TSD.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.


Company Continental Oil Company
Address Box 68, Dulce, New Mexico

By _____
Title District Superintendent

Las Cruces

(SUBMIT IN TRIPLICATE)

Land Office LC 030467
Lease No. NAFU
Unit _____



UNITED STATES
DEPARTMENT OF THE INTERIOR

GEOLOGICAL SURVEY
OCT 11 11 2:48

SUNDRY NOTICES AND REPORTS ON WELLS

| | |
|--|---|
| NOTICE OF INTENTION TO DRILL..... | SUBSEQUENT REPORT OF WATER SHUT-OFF..... |
| NOTICE OF INTENTION TO CHANGE PLANS..... | SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING..... |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF..... | SUBSEQUENT REPORT OF ALTERING CASING..... |
| NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL..... | SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR..... |
| NOTICE OF INTENTION TO SHOOT OR ACIDIZE..... | SUBSEQUENT REPORT OF ABANDONMENT..... |
| NOTICE OF INTENTION TO PULL OR ALTER CASING..... | SUPPLEMENTARY WELL HISTORY..... |
| NOTICE OF INTENTION TO ABANDON WELL..... | |
| Notice of Intention to Plug <input checked="" type="checkbox"/> | |

and Abandon

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Vaughan A-14

October 9, 1956

Well No. 6 is located 1980 ft. from N line and 1980 ft. from E line of sec. 14

36/4 Sec 14

24 S 36 E

NAFM

(1/4 Sec. and Sec. No.)

(Twp.)

(Range)

(Meridian)

Jalisco

Lea

New Mexico

(Field)

(County or Subdivision)

(State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

This well has become uneconomical to operate and is now TSD. No remedial work is considered feasible. Permission is requested to plug and abandon this well in the following manner: Set cement retainer at 2915' and cement squeeze perforations 2965-3180'; shoot off 5 1/2" casing at 1650'; fill hole with 12.5 pound mud to 1700'; set cement plug 50' below to 50' above where 5 1/2" casing was shot off; fill hole with 12.5 pound mud to within 50' of surface; set 50' plug at surface and erect 4' marker; restore location to original condition.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Continental Oil Company

Address Box 68

Elmice, New Mexico

By R. G. Kelleman
Title District Superintendent