



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. LC 069025
Unit Sand Hills

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	X
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Sept. 11, 1958

Well No. 4-Unit is located 660 ft. from N line and 600 ft. from E line of sec. 5
NE/4 of NE/4 of Sec. 5 T26S R36E.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wildcat Lea New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well drilled to T.D. 4015', cored, Drill Stem Test; Schlumberger, Sonic and Laterolog, run to total depth. Cement plugs set #1, Top of Surface casing, #2, Bottom Surface 300', #3, 62230', #4 63280, #5 64000', used 20 sacks cement with each plug.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Torredor Royalty Corporation
Address Agent for Sinclair Oil & Gas Co.
Tower Pet. Bldg.
Dallas 1, Texas
By [Signature]
Title Production Sup't.