	<u> </u>	NE	W MEXICO	0 01L C	CONSE	RVA		COMMISSI	U ON		FORM C-103
											(Rev 3-55)
	-	1					-	WELLS			
		(Sybmit t	o appropria	ite Distri		1	- <b>e</b> ii	mission Ru	le 1106)		
Name of Company BALSON Ha COBB								lland Nat'l Bank Bldg. Midland, Tex			
Lease	ulf State		We	11 No.	Unit 1	<b>I</b> <sup>etter</sup>	Section	Township 2	65	Rang	° 365
Date Work F	73/60 <sup>d</sup>	Pool					·	County	· · · · · · · ·		· · · · · · · · · · · · · · · · · · ·
			THIS IS A	REPORT	<b>OF:</b> (	Check a	appropria	te block)		·	······································
	ing Drilling Ope	rations		ng Test ar		ent Job	[	Other (E	Explain):		
Detailed account of work done, nature and quantity of materials											
Locatio	m cleaned	and level	Let and 1	regulat	100 9	arke)	<b>198</b> -				
Witnessed b	Witnessed by Position							Company Ormand Bros. Drilling Co.			
	Den Ornen		L IN BELO	WFORF	REMED	IAL W	ORK RI	PORTS OF	1		
					INAL W	ELL D	ATA			Ic	
D F Elev. T D		TD	PBTD		D			Producing Interve		val Completion Date	
Tubing Diameter Tubing		Tubing	g Depth		C	Oil String Diame		eter Oil		String Depth	
Perforated I	nterval(s)	, <u>I</u> , .			I		<u></u>				······································
Open Hole Interval						Producing Formation(s)					
				RESUL	TS OF	WORK	OVER				
Test	Date of Test		Production BPD		Product C F P D			Production PD	GO Cubic fe		Gas Well Potential MCFPD
Before Workover									-4	· . <b>-</b> · · ·	
After Workover											
		ERVATION CO	DMMISSION	<del></del>				y that the in my knowledg		iven abov	e is true and complet
Approved by Leslie A. Chemente						Name Agent					
Title	· · ·	۹۰ همینی را م ۱۰		<u>-</u>		Positio	_		· , · •••		
Date						Company DALTON H. COBB					

.