Submit 3 Copies to Approriate District

State of New Mexico Energy, Minerals and Natural Resouces

FORM C-103

DISTRICT I

					r	arriand March	25 1000		
625 N. French Dr., Hobbs, NM 88240			F	Revised March	23, 1999				
DISTRICT II	OIL CONSERVATION	ON DIVISION	N	WELL API NO.	10				
B11 South First, Artesia, NM 88210	1220 South St. Fr	30-025	5-1059						
DISTRICT III	Santa Fe, NM		Indicate Type of	_	-				
1000 Rio Brazos Rd., Aztec, NM 87410		☐ STATE ☑ FEE							
DISTRICTIV				 State Oil & Gas 1 	Lease No.				
1220 South St. Francis Dr., Santa Fe, NM 87505									
SUNDRY NOTICES AND REPORTS ON WELLS									
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH					7. Lease Name or Unit Agreement Name Skelly Penrose A Unit				
PROPOSALS.)									
1. Type of Well:									
☑ OIL WELL ☐ GAS WE	LL OTHER								
2. Name of Operator				8. Well No.					
Apache Corporation					38				
Idress of Operator 9. Pool name or Wildcat									
2000 Post Oak Blvd., Ste. 100, Houston,	Texas 77056-4400			Langlie-Ma	ttix; 7Rive	rs-Queen-Gray	burg		
Well Location Unit Letter N : 740	Feet From The South	Line and	2000	Feet From The	West	Line			
Section 3 Township	23S Range		NMPM	Lea	County	•			
	10. Elevation (Show whether DF, RI 3297' GR	KB, RT, GR, etc.)							
	Check Appropriate B	ox to Indicate Natu	re of Notice,	Report, or Othe	r Data				
NOTICE OF INTENTION	SEQUENT REPORT OF:								

Remedial Work ☐ Altering Casing Perform Remedial Work Plug and Abandon Plug and Abandonment Commence Drilling Operations Change Plans ☐ Temporarily Abandon Pull or Alter Casing ☐ Casing Test and Cement Job ✓ Other Other Request TA Status

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Apache requests approval of Temporary Abandoned status for the Skelly Penrose A Unit # 38 well.

2/5/01

CIBP set @ 3272'

2/12/01

Performed Casing Integrity Test @ 560# for 30 minutes - OK. Test witnessed by Buddy Hill - NM/OCD

See chart attached

This wellbore will be evaluated for utilization in continued unit development.

1 hh	and complete to the best of my knowledge and belief.		Sr. Engineering Techn	ioion	DATE 2/15/01
TYPE OR PRINT NAME Debra J. A	Anderson	TITLE	51. Engineering Techni	TELEPHO	712 206 6248
(This space for State Use)				TELEFIC	THE NO.
APPROVED BY	TTTLE		201	DATE	- CH 2 -
CONDITIONS OF APPROVAL, IF ANY:		€:-	HY NAMES		K View
		File	10 820 世		

