


Form 9-331a
(Feb. 1951)



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office New Mexico
LC - 032452A
Lease No. _____
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 6, 1958

Hughes A-1 Lease

Well No. 6 is located 1980 ft. from S line and 660 ft. from W line of sec. _____

5/4 4
(1/4 Sec. and Sec. No.)

23S
(Twp.)

37E
(Range)

RMPH
(Meridian)

Langlo-Mattix
(Field)

Lea
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 3335 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded 10:00 A.M. 3-1-58. Drilled 12 1/4" hole to 370'. Ran 354' of 8 5/8" 32# J-55 casing and cemented with 300 sacks of neat cement with 2% calcium added. Tested casing with 700 psi 3-2-58. Held O.K. for 30 minutes. Drilling ahead. *Cement Circulated.*

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Samadan Oil Corporation

Address Box 2137

Hobbs, New Mexico

By

J. E. Jayke

Title District Engineer