

HOBBS OFFICE O. C. C.

Form C-103

Skelly Penrose "A" Unit Well No. 194 JUN 4 11 45 AM '68

Continued

-2-

Ran 2-7/8"OD tubing, found top of cement outside 7"OD casing at 2454', spotted 200 sacks cement and pulled tubing. Pressured up to 500# with 12-1/2 barrels fluid, held pressure 3 hours, released and found top of cement outside 7"OD casing at 2423'. Picked up tubing to 2300', spotted 100 sacks cement. Pulled tubing. Pressured up to 500# with 10 barrels fluid.

Ran 2-7/8"OD tubing open-ended, found top of cement inside 7"OD casing at 2144'. Raised tubing and spotted 30-sack cement plug 1220-1070' and 10-sack plug 50' to surface. Installed 4" marker and released workover rig May 24, 1968.

The pits have been filled and this location cleared and levelled.