



Scott E. Gengler
Engineering Advisor

OXY USA INC.

Box 50250, Midland, TX 79710

March 10, 1993

New Mexico Oil Conservation Division
P.O. Box 1980
Hobbs, New Mexico 88240
Attn: Jerry Sexton

Re: Mechanical Integrity Test
Skelly Penrose B Unit #21
Section 5, T-23-S, R-37-E
Lea County, New Mexico

Dear Jerry :

OXY USA Inc. has recently become the operator of the Skelly Penrose B Unit and is in the process of testing each injection well on the unit for mechanical integrity. On February 4, 1993, a mechanical integrity test was run on the Skelly Penrose B Unit #21 which is an inactive water injection well. The NMOCD was notified of this test but did not witness the test. Attached for your records is a copy of the pressure chart from the test.

If you should have any other questions about this well, please feel free to call me at (915) 685-5825.

Sincerely,

A handwritten signature in black ink, appearing to read "Scott E. Gengler", written in a cursive style.

Scott E. Gengler
Engineering Advisor
Western Region

enclosure

cc: S. Nichols

