

NUMBER OF COPIES RECEIVED	
DISTRIBUTION	
AREA	
FILE	
U.S.G.S.	
LAND OFFICE	
TRANSPORTER	OIL GAS
MIGRATION OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company Dalport Oil Corporation		Address 3471 First Natl Bank Bldg, Dallas, Texas				
Lease W. H. King	Well No. 2	Unit Letter L	Section 6	Township 23-S	Range R-37-E	
Date Work Performed July 1963	Pool Langlie-Mattix			County Lea		

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations
 ☐ Casing Test and Cement Job
 ☒ Other (Explain):
☐ Plugging
 ☐ Remedial Work
 Temporarily abandoned

Detailed account of work done, nature and quantity of materials used, and results obtained.

Pulled rods and tubing and installed swage & valve in top of
5½" casing. Tanks and pumping unit removed.

Witnessed by A. C. Magee	Position Supt	Company Dalport Oil Corporation
------------------------------------	-------------------------	---

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA

D F Elev.	T D	P B T D	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open Hole Interval		Producing Formation(s)		

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Approved by	Name
Title	Position President
Date	Company Dalport Oil Corporation