

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company Dalport Oil Corporation		Address 530 Fidelity Union Life Bldg. Dallas, Texas				
Lease W. H. King	Well No. 2	Unit Letter L	Section 6	Township 23-S	Range 37-E	
Date Work Performed 2-13-60	Pool Langlie-Mattin			County Lea		

THIS IS A REPORT OF: (Check appropriate block)

- | | | |
|--|---|--|
| <input type="checkbox"/> Beginning Drilling Operations | <input type="checkbox"/> Casing Test and Cement Job | <input checked="" type="checkbox"/> Other (Explain): |
| <input type="checkbox"/> Plugging | <input type="checkbox"/> Remedial Work | Perforating & Fracing |

Detailed account of work done, nature and quantity of materials used, and results obtained.

Perforated 3178-86; 3602-38; 3688-92; 3737-64.**Fraced with 25,000 gallons refined oil and 38,500 lbs sand.**


Witnessed by Leon Lampert	Position Geologist	Company Dalport Oil Corporation
-------------------------------------	------------------------------	---

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA					
D F Elev.	T D	P B T D	Producing Interval	Completion Date	
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth		
Perforated Interval(s)					
Open Hole Interval			Producing Formation(s)		

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION		I hereby certify that the information given above is true and complete to the best of my knowledge.	
Approved by 	Name W. E. Teague		
Title President	Position President		
Date	Company Dalport Oil Corporation		