## NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103 (Rev 3-55)

## MISCELLANEOUS REPORTS ON WELLS PATTER DEFICE DOC

(Submit to appropriate District Office as per Commission Rule 1106)

			die District Of	rrice as	per Co	mmission R	ule I	106)				
Name of Company Dalport Oil Corporation					Address 1990 FEB 17 PM 3 08 930 Fidelity Union Life Bldg. Dallas, Texas							
	H. King	W	Vell No. Uni	t Letter		n Township			Range 37-			
Date Work Pe	rformed LO-60	Pool La	nglie Matti	ix		County		L				
	<del></del>	<del></del>	A REPORT OF:		abba-b-i	1						
Beginni	ng Drilling Operatio		ing Test and Ce			Other (	E 1 -			<del></del>		
Plugging Remedial Work					,	Other (1	схріа	in):				
Detailed acc	ount of work done, n	ature and quantity of	f materials used	and res	ults obt	ained.			· - · - · · ·			
	mented 3770° - Ch 1600∦s - Te	5 1/2" 14# c	asing with	<b>3</b> 00 g	acks.	Tested	on a	2-12-60				
Witnessed by Leon Lampert FILL IN BEL			Position Geologi		ORK R	Company Dalport Oil Corporation EPORTS ONLY						
			ORIGINAL			-	· LI	<del> </del>				
D F Elev. T D			PBTO			Producing Interval		Comp	Completion Date			
Tubing Diameter Tubing De		Tubing Depth	Oi		ng Diame	ter Oil		Oil String l	String Depth			
Perforated Int	erval(s)	<del> </del>		<del></del>	<del>,</del>							
Open Hole Interval					Producing Formation(s)							
			RESULTS OF	WORK	OVER					· <del></del>		
Test	Date of Test	Oil Production BPD	Gas Produc MCFPI	tion D		roduction PD	Cul	GOR pic feet/Bbl	G	as Well Poten MCFPD	tial	
Before Workover												
After Workover											<del></del>	
OIL CONSERVATION COMMISSION					I hereby certify that the information given above is true and complete to the best of my knowledge.							
Approved by					Name (1) Tours							
Title		/		Positio		idont			<i>H</i> •	·		
Date					ny	ident ORT OIL (	CORP	ORATION				