

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

HOBBS OFFICE OCC

| | | | | | |
|---|-----------------------|--|---------------------|------------------------|--------------------|
| Name of Company Continental Oil Company | | Address Box 68, Eunice, New Mexico | | | |
| Lease Stevens B-7 | Well No. 2 | Unit Letter J | Section 7 | Township 13N | Range 7E |
| Date Work Performed 12-26-59 | Pool Jalpat | County Lea | | | |

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations ☐ Casing Test and Cement Job ☐ Other (Explain):
☐ Plugging ☒ Remedial Work


Detailed account of work done, nature and quantity of materials used, and results obtained.

Ran 2" tubing, set at 3321.

Job started 12-26-59 Comp 12-27-59

Approved by USGS: January 5, 1960

LC 030556 b

| | | | | | | |
|--|--------------|-------------------------------------|------------------------|---|--------------------|--------------------------|
| Witnessed by L. R. Clayton | | Position Drilling Foreman | | Company Continental Oil Company | | |
| FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY | | | | | | |
| ORIGINAL WELL DATA | | | | | | |
| D F Elev. | T D | P B T D | | Producing Interval | Completion Date | |
| Tubing Diameter | | Tubing Depth | | Oil String Diameter | Oil String Depth | |
| Perforated Interval(s) | | | | | | |
| Open Hole Interval | | | Producing Formation(s) | | | |
| RESULTS OF WORKOVER | | | | | | |
| Test | Date of Test | Oil Production BPD | Gas Production MCFPD | Water Production BPD | GOR Cubic feet/Bbl | Gas Well Potential MCFPD |
| Before Workover | | | | | | |
| After Workover | | | | | | |
| OIL CONSERVATION COMMISSION | | | | I hereby certify that the information given above is true and complete to the best of my knowledge.  | | |
| Approved by | | | | Name J. R. Parker | | |
| Title | | | | Position District Superintendent | | |
| Date | | | | Company Continental Oil Company | | |