



Scott E. Gengler  
Engineering Advisor

OXY USA INC.

Box 50250, Midland, TX 79710

March 10, 1993

New Mexico Oil Conservation Division  
P.O. Box 1980  
Hobbs, New Mexico 88240  
Attn: Jerry Sexton

Re: Mechanical Integrity Test  
Skelly Penrose B Unit #45  
Section 8, T-23-S, R-37-E  
Lea County, New Mexico

Dear Jerry :

OXY USA Inc. has recently become the operator of the Skelly Penrose B Unit and is in the process of testing each injection well on the unit for mechanical integrity. On February 4, 1993, a mechanical integrity test was run on the Skelly Penrose B Unit #45 which is an active water injection well. The NMOCDD was notified of this test but did not witness the test. Attached for your records is a copy of the pressure chart from the test.

If you should have any other questions about this well, please feel free to call me at (915) 685-5825.

Sincerely,

A handwritten signature in dark ink, appearing to read "Scott E. Gengler", written over a horizontal line.

Scott E. Gengler  
Engineering Advisor  
Western Region

enclosure

cc: S. Nichols

