


Form 9-531a
(Feb. 1957)



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Cruces
Lease No. 030186 (b)
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT X
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 14, 1956

Well No. 1 is located 1980 ft. from 1000 line and 1980 ft. from 1000 line of sec. 14

34 1/2 Sec. 14
(1/4 Sec. and Sec. No.)

23S
(Twp.)

37E
(Range)

T10N
(Meridian)

Cline, Devonian
(Field)

Lea
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 3283 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Ran 9 sacks cement from 3640-3663 and 10 sacks at surface. Set 8' piece of 5 1/2" pipe 4' below and 4' above surface.

FINAL REPORT

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company WELSH-TAYLOR OIL CORPORATION

Address Box 1821

Midland, Texas

By A. A. Bolton
District Superintendent

Title _____