

DUPLICATE

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

AUG 1 PM 3:11

COMPANY Resler & Sheldon 302 Carper Building, Artesia, New Mexico
(Address)

LEASE Kelly State WELL NO. 3 UNIT M S 16 T 23 R 37
DATE WORK PERFORMED _____ POOL Langlie-Mattix

This is a Report of: (Check appropriate block) ☒ Results of Test of Casing Shut-off
☐ Beginning Drilling Operations ☐ Remedial Work
☐ Plugging ☒ Other Completion

Detailed account of work done, nature and quantity of materials used and results obtained.

Set cement plug from 2050' to 1680'. Set whipstock and drilled out in new hole. Drilled to 3627'. Set 7" casing at 3627' and cemented with 600 sacks, the first 400 sacks containing 4% gelatin. Drilled out to 3624'. Ran gamma-neutron log. Perforated from 3617-09', 3588-81' and from 3568-55'. Treated each zone separately with 10,000 gallons lease crude and 20,000 lbs. sand. Mixed 1/10th pound adomite per gallon to lease crude.

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl Date _____
Tbng. Dia _____ Tbng Depth _____ Oil String Dia _____ Oil String Depth _____
Perf Interval (s) _____
Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:

	BEFORE	AFTER
Date of Test	_____	_____
Oil Production, bbls. per day	_____	_____
Gas Production, Mcf per day	_____	_____
Water Production, bbls. per day	_____	_____
Gas-Oil Ratio, cu. ft. per bbl.	_____	_____
Gas Well Potential, Mcf per day	_____	_____
Witnessed by _____		

(Company)

OIL CONSERVATION COMMISSION

Name [Signature]
Title _____
Date AUG 2 1956

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name [Signature]
Position Partner
Company Resler & Sheldon