



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office LC  
Lease No. 032852 (n)  
Unit \_\_\_\_\_

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 21, 1955

Well No. 5 is located 1980 ft. from [N] line and 1200 ft. from [W] line of sec. 17

17 of Section 17 23 North 17 East  
(Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Salust & Purrose Shelly Pools Lee New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3329 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spud date: March 16, 1955

Cactus Drilling Company, Contractor, drilled to 1160 feet. Set 36 joints of 8-5/8 OD 3-55; 24' surface casing at 1139 feet rotary measurement. Cemented with 350 sacks regular cement. Cement circulated. Waited on cement 24 hours then tested with 1000' psig, held 30 minutes. No leaks. No decrease in pressure.

ILLEGIBLE

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Cactus Oil Corporation

Address Box 929

Armore

Oklahoma

By T. C. Craighead

Title T. C. Craighead  
Production Clerk