

(SUBMIT IN TRIPLICATE)

Land Office Las Cruces

Lease No. LC 630566

Unit NMPL

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		ILLEGIBLE	
NOTICE OF INTENTION TO CHANGE PLANS			
NOTICE OF INTENTION TO TEST WATER SHUT-OFF			
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL			SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE			SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING			SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL			
Subsequent Report of cleanout and sandfree			X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Stevens 8-18 Unit

April 15, 1958

Well No. 1 is located 990 ft. from N line and 1650 ft. from E line of sec. 18

NE 1/4 Section 18 23S 37E NMPL
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Lea New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3349 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

ELPONS WORKOVER: TD Bolo and Sand 3660', PB 3050', DF 10', elev 3349' DF. Ray Yates 2689-3050' Open Hole. Casing point 5 1/2" at 2689'. Prior to workover well was on marginal status. November, 1957, production was 79 MCF gas.

WORK DONE: Cleaned out 2730-3050'. 2 1/2" tubing at 2710'. Failed to recover load. Well dead.

WELL WORKOVER: TD, Bolo, DF, elev, Ray and Cag. pt. same as before workover. Well was pending additional remedial work. Workover started 1-11-58, completed 1-27-58. was not tested.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Continental Oil Company

Address Box 68

Unico, New Mexico

By _____

Title District Superintendent