

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
----------------------------	--------------------------------	---

5. State Oil & Gas Lease No.

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> <b>Temporarily Abandoned</b>	7. Unit Agreement Name
2. Name of Operator <b>Resler and Sheldon</b>	8. Farm or Lease Name <b>Steeler A</b>
3. Address of Operator <b>314 Carper Bldg. Artesia, New Mexico</b>	9. Well No. <b>2</b>
4. Location of Well UNIT LETTER <b>M</b> <b>660</b> FEET FROM THE <b>south</b> LINE AND <b>660</b> FEET FROM THE <b>west</b> LINE, SECTION <b>20</b> TOWNSHIP <b>238</b> RANGE <b>37E</b> NMPM.	10. Field and Pool, or Wildcat <b>Jalnet</b>
15. Elevation (Show whether DF, RT, GR, etc.)	12. County <b>Lea</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐

TEMPORARILY ABANDON ☐

PULL OR ALTER CASING ☐

OTHER ☐

PLUG AND ABANDON ☒

CHANGE PLANS ☐

REMEDIAL WORK ☐

COMMENCE DRILLING OPNS. ☐

CASING TEST AND CEMENT JOB ☐

OTHER ☐

ALTERING CASING ☐

PLUG AND ABANDONMENT ☐

**Re-entering** ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Rigged up Eunice Well Service Inc. pulling unit. Knocked out surface plug and ran sand pump to an approximate depth of 1400' which is some 200' below Top of Rustler Anhydrite. Bailed and spudded for 10 or 12 hours. Could not make any headway although all mud was removed. In other words we bailed fairly clean water but could not bail or spud deeper. A hard, firm bottom. Effort abandoned.

Reference is made to Commission letters of October 28, 1957, June 9th, 1960 and June 16th, 1960. We believe, based on these letters that an acceptable program of plugging would call for 25 sack plug in and out of the base of the 9 5/8ths casing (694') and the 10 sack cap with permanent marker. The hard, firm bridge at 1400' is just at top of salt and is sealing off the salt from upper waters. We so propose to plug and abandon.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED John W. Runyan TITLE **Co Owner**

DATE **12-5-70**

APPROVED BY John W. Runyan TITLE **Geologist**

DATE **DEC 7 1970**

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

DEC 7 1970

OIL CONSERVATION COM.  
WASHINGTON, D.C.