

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS

NOV 1 1957 15 AM 9:44

(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY RESLER & SHELTON 302 Carper Building, Artesia, New Mexico
(Address)

LEASE Stealer "A" WELL NO. 2 UNIT N S 20 T 238 R 37E

DATE WORK PERFORMED Oct. 1 thru 7, 1957 POOL Langlie-Mattix

This is a Report of: (Check appropriate block) ☐ Results of Test of Casing Shut-off
☐ Beginning Drilling Operations ☐ Remedial Work
☒ Plugging ☐ Other _____

Detailed account of work done, nature and quantity of materials used and results obtained.

As you were notified on C-101, September 17, 1957, Stealer "A" #2 was entered and cleaned out to 2511'. Could not enter 7" stub as tools side tracked. ~~XXXXXXXXXXXX~~
~~XXXXXXXXXXXX~~ Hole left full of mud. The 9 5/8" is cemented at 694' and has all fresh water isolated. TEMPORARILY ABANDONED.

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:
DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl Date _____
Tbng. Dia _____ Tbng Depth _____ Oil String Dia _____ Oil String Depth _____
Perf Interval (s) _____
Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:	BEFORE	AFTER
Date of Test	_____	_____
Oil Production, bbls. per day	_____	_____
Gas Production, Mcf per day	_____	_____
Water Production, bbls. per day	_____	_____
Gas-Oil Ratio, cu. ft. per bbl.	_____	_____
Gas Well Potential, Mcf per day	_____	_____
Witnessed by _____		

(Company)

OIL CONSERVATION COMMISSION
Name [Signature]
Title _____
Date _____

I hereby certify that the information given above is true and complete to the best of my knowledge.
Name [Signature]
Position Partner
Company RESLER & SHELTON

THE COMMISSION MUST BE NOTIFIED EVERY 6 MONTHS ON FORM C-103 AS TO THE WELL STATUS AND YOUR FUTURE PLANS FOR THIS WELL.