

## NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103  
(Rev 3-55)

## MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company <b>Resler and Sheldon</b>		Address <b>302 Carper Building, Artesia, New Mex.</b>					
Lease <b>May B</b>	Well No. <b>1</b>	Unit <b>L</b>	Letter <b>21</b>	Section <b>23S</b>	Township <b>37E</b>	Range <b>37E</b>	
Date Work Performed <b>April 20</b>	Pool <b>Teague Grayburg</b>		County <b>Lea</b>				

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations    ☐ Casing Test and Cement Job    ☐ Other (Explain):  
☐ Plugging    ☒ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

Acidized perms from 3648 to 3689 w/ 1000 gallons jelled acid. Before treatment well had about stopped producing mainly due to a lime deposit. Since treatment production has slowly increased.

Witnessed by <b>Jimmy Evans</b>	Position <b>Supt.</b>	Company <b>Resler and Sheldon</b>
------------------------------------	--------------------------	--------------------------------------

## FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY


## ORIGINAL WELL DATA

D F Elev.	T D	P B T D	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open Hole Interval		Producing Formation(s)		

## RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover	5-2-59	2	3.74	0	1870	
After Workover	July 59	20	70	0	3500	

OIL CONSERVATION COMMISSION

Approved by 	I hereby certify that the information given above is true and complete to the best of my knowledge.
Title	Name <b>Wilas Sheldon</b>
Date	Position <b>Partner</b>
	Company <b>Resler and Sheldon</b>