

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY RESLER & SHELTON 302 Carper Bldg., Artesia, New Mexico
(Address)

LEASE May "B" WELL NO. 1 UNIT L S 21 T 238 R 37E

DATE WORK PERFORMED Aug. 30 thru POOL Undesignated
Sept. 4, 1957

This is a Report of: (Check appropriate block) ☒ Results of Test of Casing Shut-off

☐ Beginning Drilling Operations

☐ Remedial Work

☐ Plugging

☒ Other Completion

Detailed account of work done, nature and quantity of materials used and results obtained.

Drilled 8 7/8" hole to 3630'. Cased 6 3/4" to 3689'. Ran 5 1/2" 14# J-55 casing to 3689' and cemented w/400 sax. Cemented August 30, 1957. After 48 hours pressured to 1000 psi. Held OK for 30 minutes. Drilled out to 3689' and tested for 30 minutes at 1000 psi. OK. Ran Gamma-Ray log and perforated 3512-14, 3518-23, 3537-41, 3648-55, 3668-74 and 3685-89. Treated lower three sets of perforations w/633 gals. regular acid each using straddle packers. Then sand oiled upper three sets perforations with 10,000 gallons lease crude and 14,000 lbs. sand, treated down annular space above packer set at 3550'. Packer removed and well completed.

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl Date _____

Tbng. Dia _____ Tbng Depth _____ Oil String Dia _____ Oil String Depth _____

Perf Interval (s) _____

Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:

BEFORE

AFTER

Date of Test

Oil Production, bbls. per day

Gas Production, Mcf per day

Water Production, bbls. per day

Gas-Oil Ratio, cu. ft. per bbl.

Gas Well Potential, Mcf per day

Witnessed by _____

(Company)

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name E. J. Resler

Name Delas Sheldon

Title Manager

Position Partner

Date August 30, 1957

Company RESLER & SHELTON