

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Las Cruces

Lease No. 030187

Unit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

November 1, 1948

Well No. La Munion 7 is located 660 ft. from N line and 660 ft. from E line of sec. 22

SW of 22 (1/4 Sec. and Sec. No.) 233 (Twp.) 37E (Range) 11N (Meridian)

Doña Ana (Field) Las (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is        ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

After waiting forty-eight hours, the 9-5/8" casing was tested with 1200# pressure applied for 30 minutes. The plug was drilled and the casing and cement were tested with 1200# pressure applied for 30 minutes. Both tests were OK, and preparations were made to drill ahead.

Top of cement back of 9-5/8" cas = 885' per temperature survey.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Gulf Oil Corporation

Address P. O. Box 1667

Hobbs, New Mexico

By

E. J. Gallagher

Title

District Sup't.