Form 9-331 a (March 1942)

(SUBMIT IN TRIPLICATE) UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

	Office Las Cruces
Lease	No. 030187

Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

ĺ	NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF.						
	NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING						
	NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING						
	NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR						
	NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT						
	NOTICE OF INTENTION TO PULL OR ALTER CASING.	SUPPLEMENTARY WELL HISTORY						
	NOTICE OF INTENTION TO ABANDON WELL							
	(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)							
		Setabor 18 Inte						
		October 18, , 1948						
	to Manusco a							

		66 : ft. from $\left\{ \begin{matrix} \mathbf{E} \\ \mathbf{W} \end{matrix} \right\}$ line of sec. 22
(14 Sec. and Sec. No.)	(Twp.) (Range)	(Meridian)
(Field)	(County or Subdivision)	(State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

After waiting thirty-six hours, the casing war tested with 500% pressure applied for 30 minutes. The plug was drilled and the casing tested with 500% pressure applied for 30 minutes. Both tests were 0%, and preparations are being sade to drill about.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Oulf 01 Corporation

Address Box 1667

Hobbs, New Nexteo

By	8.J. /	Zalla	the
- 	Hatrict	Sunte	

Title____istrict Sup't.

U. S. GOVERNMENT PRINTING OFFICE 16-8437-3