
LAS Cruces

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY



SUNDRY NOTICES AND REPORTS ON WELL

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT.
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	***************************************
	<u> </u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

			orvary 10, 14	·9	, 19
Lakunyon Well No. 8 is loo	cated 660 ft.	from ${\mathbb{S} \atop S}$ line a	nd 1980 ft. from	n W line of se	c. 22
(% Sec. and Sec. No.)		(Range)	(Meridian)	Mexico	
(Field)	***************************************	nty or Subdivision)		(State or Territory)	

The elevation of the derrick floor above sea level is 32961 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

After waiting forty-eight hours, the 9-5/8" casing was tested with 1200# pressure applied for 30 minutes. The plug was drilled and the easing and cement were tested with 1200# pressure applied for 30 minutes. Both tests were OK, and preparations were made to drill ahead.

No pressure drop)

Top of cement back of 9 5/8" csg @ 1930' per temperature survey.

978"- 2900"

Form 9-881 a (March 1942)

Company.	Gulf Oil Corporation	
Address	P. O. Bax 1667	
	Hobbs, New Mexico	By & Gallagher
,		Title District Sup!t