

DETAILS OF CORE

Report of Coring - Core #1 - 9266' to 9326' - Cutting time 31 hrs, 56 minutes, recovered 60'. Top 8'4", medium, round, shaly sandstone. Very scattered light stain. Next 12'3", coarse, hard, clean sandstone. Moderate overall stain. Saturated. Basal 3'6" shaly. Next 26'2", green shale. Scattered zones of barren, very shaly sandstone. Bottom 13'3", medium to coarse, slightly shaly to clean sandstone. Good porosity and stain. Saturated.

Report of Coring - Core #2 - 9326' to 9386' - Cutting time 12 hours, 32 minutes, recovered 60'. Top 7', fine to coarse, round, slightly shaly to clean sandstone. Scattered dark stain. Saturated. Next 1'9", fine, shaly, hard sandstone. Barren. Next 1'2", dark grey shale. Next 34'4", coarse, round very shaly, friable sandstone. Barren. Next 6'5", medium to coarse, clean, friable sandstone. Good porosity. Light overall stain. Bottom 9'4", coarse, round, shaly, friable sandstone. Scattered stain and porosity in basal 6".

Report of Coring - Core #3 - 9386' to 9446' - Cutting time 16 hours, 14 minutes, recovered 60'. Top 21'6", medium to coarse, slightly shaly to clean, friable sandstone. Scattered stain. Good porosity. Next 12'6", fine to medium, round, shaly, sandstone. Barren. Next 12'4", fine to coarse, slightly shaly, friable, sandstone. Fair porosity. Light scattered stain. Next 6'6", coarse, round, calcareous sandstone. Barren. Next 2'4", green shale. Next 4'2", green, fine, shaly sandstone. Barren. Bottom 8", green shale.