

Form 9-381a
(March 1942)

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Cruces
Lease No. 030187
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....		SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 31, 1949

LaMunyon
Well No. 10 is located 1650 ft. from S line and 970 ft. from W line of sec. 22

SW 1/4 of 22 235 37E RMPM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Teague Lea New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On May 26 & 27, 1949, ran 9 jts of new 13 3/8" OD, 48#, 8 Rt Thd, H-40, R-2, 38 casing w/short Threads and Collars. Tallies 287', H-18', set @ 305'. Cemented by Halliburton w/300 sacks of common Portland pack cement. Plug @ 285'. Cement circulated OK. Job started @ 10:45 p.m. and completed @ 3:15 a.m. After waiting thirty-six hours, the 13 3/8" casing was tested @ 285' with 600# pressure applied for 30 minutes. The plug was drilled and the casing and cement tested @ TD 309' with 400# pressure applied for 30 minutes. There was no pressure drop on either test, and preparations are being made to drill ahead.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Gulf Oil Corporation

Address P. O. Box 1667

Hobbs, New Mexico

By _____

Title District Sup't