

U.S. G.S. FORM  
100-100-100

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE  
(Other instructions on  
reverse side)

Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-030187

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back or a different formation.  
Use "APPLICATION FOR PERMIT--" for such proposals.)

RECEIVED

JAN 23 1981

7. TYPE OF WELL ☐ GAS ☒ OTHER

8. NAME OF OPERATOR

Gulf Oil Corporation

9. ADDRESS OF OPERATOR

P. O. Box 670, Hobbs, NM 88240

10. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.)

Section space (7 below.)

At surface

1980' FNL & 1980' FWL

11. PERMIT NO.

12. ELEVATIONS (Show whether DE, RT, GR, etc.)

3284' GL

13. FARM OR LEASE NAME

C. E. LaMunyon

14. WELL NO.

13

15. FIELD AND POOL, OR WILDCAT

Imperial Tubb Drinkard

16. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec 27-T23S-R37E

17. COUNTY OR PARISH 18. STATE

Lea

NM

19. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐

PULL OR ALTER CASING ☐

FRACTURE TREAT ☐

MULTIPLE COMPLETE ☐

SHOOT OR ACIDIZE ☐

ABANDON\* ☐

REPAIR WELL ☐

CHANGE PLANS ☐

(Other) ☐

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT\* ☐

(Other) Attempted Completion ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

20. PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

Set RBP at 6486'. Perf 6419-23' and 6470-74', bottom tubing at 6459'. Ran pump and rods. Hung well on. Pumped 0 BO and 275 BW in 24 hours. POH with rods, RBP and tubing. Ran 2-7.8" tubing, and rods, clamped off. Complete after unsuccessful completion in Tubb Drinkard 1-13-81.

21. I hereby certify that the foregoing is true and correct

SIGNED

*R. P. Pite*

TITLE

Area Engineer

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

ACCEPTED FOR REC'D 23-81

DATE

JAN 30 1981

U.S. GEOLOGICAL SURVEY  
HOBBS, NEW MEXICO